

The National Locksmith Guide to Safe Opening
Volumes 1 - 5

Purchase Here

<http://www.thenationallocksmith.com/index.asp?page=stp,safe>



Decoding Instructions: See below

VERY IMPORTANT!!!!

Thank you for purchasing The National Locksmith Guide to SAFE OPENING. We are sure the book will help you many times. Please read this letter very carefully. Here is some important information on how to use this book.

ALL THE DRILLING INFORMATION IN THE SAFE LISTING IS CODED!! This has been done so that if you lose your book or if it is stolen, it cannot be used to help a thief. In the listing section, each measurement that has been given for drilling purposes has had one inch added to the real measurement. To decode the true measurement to drill just subtract one inch from the measurements given in the book. Only drilling information has been coded in this way.

Door thickness to lock has not been coded. Door thickness to bolt center has not been coded. Type of lock has not been coded. Drop-in point has not been coded.

Drill point has been coded...subtract 1" from the measurement given in the listing to obtain the true measurement. Example: Drill point given in listing—97 x 2". The true decoded measurement would be 97 x 1". Relocker drill points have also been coded throughout this book. Example: Relocker drill point in listing—2-1/2"LC, 3-1/4" up. The true decoded measurement would be 1-1/2"LC, 2-1/4" up.

Some drill points and relocker drill points are given in the service notes column. These are coded measurements. Subtract 1" as in the above examples. Remember, unless indicated otherwise, all drill points and relocker drill points are taken from dial center.

The chapters in the back of this book give actual drill points and relocker drill points. So not try and decode any measurement in these chapters: Opening A Mosler Bahmann or Safe Opening Seminar. True measurements are given in these two chapters. They were not coded.

PLEASE DO NOT KEEP THIS LETTER WITH YOUR BOOK. FILE IT SOMEWHERE SAFE.

Unfortunately, errors can appear in a book like this since there are so many details to contend with. Please correct the mistakes by writing in the correct information in your copy of the book.

1. p. 141 Under Service Notes--Dial to handle measurement should read approx. 4".
2. p. 153 Relocker drill point--there is a secondary relocker. RLDP for this is: 5-1/2" LC x 2-1/4" up.
3. p. 169 Door thickness to bolt center should read 2-3/4".
4. p. 184 Under Service Notes--dial center to handle center should read 4".
5. p. 30 should be titled "Electronic Home Safe." It is NOT imported.